



MODEL P510A ANALOG TRANSMITTER

USING A POTIOMETER INPUT AS SHOWN BELOW, THE OUTPUT IS 4-20 MILLIAMPS.

ALTERNATIVELY, 0 TO 5VDC CONTROL SIGNAL MAY BE USED INSTEAD OF THE POT. CONNECT THE CONTROL SIGNAL TO TERMINAL 1 AND THE COMMON TO TERMINAL 2. USE THE JUMPER AS SHOWN BELOW FOR AN OUTPUT SELECTION OF 0 TO 20 MA OR 4 TO 20 MA.

THE UNIT MUST BE POWERED WITH 9 TO 30VDC ON TERINALS 7 (+) AND 8 (-).

